

# Produktinformation:

**Varenavn:**

Boiler isolering EPDM 670x330x13 mm

**Varenr:**

G91508

**Pris:**

295,40 DKK /stk

**Link:**<https://gastroparts.dk/shop/p/boiler-isolering-epdm-670x330x13-mm-G91508>**Beskrivelse:**

Boiler isolering EPDM 670x330x13 mm

**Mål:**

- Længde: 670 mm
- Bredde: 330 mm
- Højde: 13 mm
- Vægt: 200 gr

**Fabrikater:****• ELECTROLUX / ZANUSSI**

Dishwashing/Undercounter ET5E (698076), ET5ED (698077), ET5EDCW (698010), ET5EDF (698090), ET5EDG (698004), ET5EDWS (698084), FL620ADPWS (698014), FL620DPWWS (698027), FL620EA (698070), FL620EA/DD (698079), FL620EADP (698071), FL620EADP/ (698080), FL620EAG (698026), FL620EP (698003), FL620EP/DD (698078), FL700 (698015), H1310SANA (698016), H3300 (698007), HYDRA700 (727015), LS61 (502000), LS61/60 (502002), LS62 (502100), LS62/1P (502108), LS62/60 (502106), LS62/UK (502116), LS62/UKRP (502102), LS62D (502101), LS62F (502103), LS62HD (502109), LS63 (502200), LS63/1P (502207), LS63/60 (502206), LS63/UK (502208), LS63/UKRP (502202), LS63D (502201), LS63F (502203), LS64 (502300), LS64/1P (502305), LS64/UK (502306), LS64/UKRP (502301), LS65 (502114), LS6EA (502520), LS6EA/60 (502041), LS6EA/DP (502521), LS6EA/DPDD (502006), LS6EA/DPUK (502031), LS6EA/UK (502030), LS6EADD (502005), LS6EADP3 (502009), LS6EADPDWS (502022), LS6EADPWS (502014), LS6EADPWSG (502015), LS6EAH (502523), LS6EP (502003), LS6EP/DD (502004), LS6MCD (502524), LS6SANA (502024), LS7 (503001), LS7/1UK (503006), LS7/60 (503009), LS7/9 (503007), LS7/DP (503008), LS7D (503000), LS7DEK (503005), LS7F (503004), LS7HD (503012), LS7UK/RP (503002), LV62 (502104), LV63 (502204), LV64 (502302), LV6EA (698081), LV6EADP (698082), LV6EADPWS (698011), LV6EP (698006), LV70 (503003), PH4/WT40 (503016), PH4RBP/WT40 (503017), WT32/UK (502409), WT33/UK (502510), WT34/UK (502609), WT35 (502408), WT37 (502111), WT37/4.5 (502117), WT37/UK (502122), WT37J50 (502219), WT37J60 (502218), WT37LEV/9 (502020), WT38 (502112), WT38/4.5 (502118), WT38/4.5NW (502129), WT38/60 (502321), WT38/M50 (502008), WT38/M60 (502322), WT38C (502125), WT38C60 (502126), WT38CUC (502127), WT38D (502110), WT38DWS (502023), WT38M50/4 (502029), WT38M60/4 (502347), WT38MED (502323), WT38MEDWS (502018), WT38PM50 (502019), WT38PM60 (502346), WT38TDE (502007), WT38UK (502217), WT38WL (502514), WT38WS (502016), WT38WSG (502017), WT40/9 (503010), WT40/9 (503010), WT40/F (503011), WT40/F (503011), WT40/J50 (503013), WT40/J60 (503014), WT40UKRP (503015), Z70 (777310), Dishwashing/Hood Type D800/6 (505018), D800/9 (505017), ECOTEMP12- (504004), ECOTEMP12INS (504065), ECOTEMP12S (504165), ECOTEMP12SW (504063), ET12E (504104), ET12E (504104), ET12EI (698057), ET12EICW (698062), ET12EICWG (698061), ET12EIF (698065), ET12EIG (698056), ET12EIS (698063), ET12EWS (504218), H1510SANA (698017), H2500 (698008), H3500 (698009), HT1000 (698051), HT1000 (698051), HT1000DP (698054), HT1000INS (698052), HT1000elm (698021), HT1200 (698050), HT1200 (698050), HT1200BIDG (698029), HT1200BIDW (698038), HT1200DEK (504129), HT1200DP (698055), HT1200INS (698053), HT1200INS (698053), HT1200INS (504109), HT1200IWS (698013), HT1200IWS (698012), HT1200elm (698020), HT800 (698025), HT800 (698025), HT900 (698022), HT900ADG1 (698028), HYDRA1000 (727021), HYDRA1200 (727020), HYDRA800 (727025), HYDRA800 (727025), LC100 (504003), LC120 (504023), LC80 (505003), LC80 (505003), LD900 (698024), LS10 (504001), LS10 (504100), LS10/1 (504006), LS10/12KW (504007), LS10/1UKRP (504010), LS10/50J (504012), LS10/60 (504005), LS10/60HZ (504105), LS10/60J (504013), LS10/HD (504015), LS10/UK1 (504018), LS10/UK3 (504019), LS10CW (504107), LS10D (504000), LS10DEK (504009), LS10DP (504014), LS10DP (504114), LS10EA (504142), LS10F (504008), LS10HD (504115), LS10INS (504108), LS10N (504080), LS10N (504111), LS10SW (504011), LS10UK/1 (504118), LS10UK/3 (504119), LS10UKDP (504102), LS10UKRP (504002), LS12 (504021), LS12 (504121), LS12/60 (504025), LS12/60HZ (504125), LS12/UK3 (504061), LS12ASIA (504190), LS12CW (504128), LS12CWIN (504178), LS12D (504020), LS12DEK (504029), LS12DP (504024), LS12DP (504122), LS12F (504028), LS12HD (504053), LS12HD (504153), LS12INS (504120), LS12MEX (504078), LS12NAU (504163), LS12UK/3CW (504161), LS12UK/RP (504022), LS12UKDPCW (504164), LS14EA (504101), LS14EA (504101), LS14EA/60 (504117), LS14EA/G (504133), LS14EAASIA (504131), LS14EADP/G (504179), LS14EAI (504110), LS14EAI/AU (504116), LS14EAI/DD (504155), LS14EAIWS (504211), LS14EAWS (504209), LS14ROW (504220), LS14ROW60 (504224), LS14SANA (504221), LS8 (505001), LS8 (505001), LS8/1UKRP (505008), LS8/1UKRP (505008), LS8/60 (505007), LS8/60 (505007), LS8/9 (505006), LS8/9 (505006), LS8/9DD (505031), LS8/9DD (505031), LS8/DP (505009), LS8/DP (505009), LS8/HD (505021), LS8/HD (505021), LS8/UK1 (505026), LS8/UK1 (505026), LS8D (505000), LS8D (505000), LS8DEK (505005), LS8DEK (505005), LS8DEK (505037), LS8DEK (505037), LS8F (505004), LS8F (505004), LS8UK/RP (505002), LS8UK/RP (505002), LS8UK3 (505027), LS8UK3 (505027), LS9ADG1 (505041), LS9AUK/3 (505034), LS9P (505022), LS9P60 (505035), LS9PAUS (505043), LS9PDD (505033), LV1000 (698059), LV1200INS (698060), LV1200IWS (698018), LV900P (698023), WT50/1 (505016), WT50/1 (505016), WT50/1UKRP (505015), WT50/1UKRP (505015), WT50/6 (505014), WT50/6 (505014), WT50/60 (505019), WT50/9 (505010), WT50/9 (505010), WT50/F9 (505012), WT50/F9 (505012), WT50/J50 (505023), WT50/J60 (505024), WT50/N (505020), WT50/UK1 (505028), WT50/UK3 (505029), WT50/UK9RF (505011), WT50/UK9RF (505011), WT55ADG1 (505042), WT55AUK/3 (505040), WT55P (505038), WT55P60 (505039), WT55PM50 (505044), WT55PM60 (505045), WT60 (504135), WT60/60HZ (504145), WT60/60HZC (504146), WT609NINS (504152), WT60ASIA (504191), WT60CW (504136), WT60DP (504134), WT60INS (504138), WT60INSCW (504139), WT60MX2206 (504177), WT60N (504151), WT60NAU (504141), WT60NAUCW (504140), WT60NAUDP (504159), WT60U40050 (504171), WT60U44060 (504172), WT60UKDPCW (504137), WT65BIDWSG (504213), WT65E (504156), WT65E60 (504169), WT65EB (504157), WT65EB60 (504170), WT65EBASIA (504174), WT65EBI (504166), WT65EBIA (504167), WT65EBID (504222), WT65EBIDG (504173), WT65EBIWS (504214), WT65EBIWS (504223), WT65EBWS (504212), WT65EI (504158), WT65EIA (504168), WT65EIM50 (504175), WT65EIM60 (504176), WT65EJ50 (504183), WT65EJ60 (504186), WT65MED (504180), WT65MEDWS (504215), WT65ROW (504219), WT65ROW60 (504225), Z80 (777430), Dishwashing/Warewashers ET830M (506045), ET830MH (506046), ET850M (506047), LV100M (698044), LV100M (698044), LV200M (698045), LV200M (698045), PW100M (698040), PW100M (698040), PW100MG (698039), PW100MHG (698043), PW100MHG (698043), PW160HZ (506012), PW1MG (506010), PW1MG (506010), PW1MHG (506013), PW1MHG (506013), PW1MUK (506011), PW1MUK (506011), PW1SMG (506007), PW200M (698041), PW200M (698041), PW200MG (698046), PW2M60 (506016), PW2M60 (506016), PW2MG (506014), PW2MG (506014), PW2MUK (506015), PW2MUK (506015), PW2SMG (506044), WT830M (506018), WT830M (506018), WT830M60G (506020), WT830M60G (506020), WT830MHG (506026), WT830MHG (506026), WT830MUK (506019),

WT830MUK (506019), WT850M (506022), WT850M (506022), WT850M60G (506024), WT850M60G (506024), WT850MUK (506023), WT850MUK (506023),

## Relateret produkter:

### Billede:



**GASTROPARTS ApS** - Håndværkervænget 19 - 2670 Greve - CVR: 39057530

Tlf.: 53704748 - Mail: [info@gastroparts.dk](mailto:info@gastroparts.dk) - Web: [www.gastroparts.dk](http://www.gastroparts.dk)

Bank: (OBS. NY BANK KONTO ) NORDEA - Regnr.: **2476** / Kontonr.: **9033464751**