

Produktinformation:

Varenavn:

Interface board WT65, PW1-2 / WT830-850, LS14EA

Varenr:

G91706

Pris:

2.485,50 DKK /stk

Link:<https://gastroparts.dk/shop/p/interface-board-wt65,-pw1-2---wt830-850,-ls14ea-G91706>**Beskrivelse:****Mål:**

- Længde: mm
- Bredde: mm
- Højde: mm
- Vægt: 200 gr

Fabrikater:**• ELECTROLUX / ZANUSSI**

Dishwasher hood type LS10 (504100), LS14EA (504101), LS10UKDP (504102), ET12E (504104), LS10/60HZ (504105), LS10CW (504107), LS10INS (504108), HT1200INS (504109), LS14EAI (504110), LS10N (504111), LS10DP (504114), LS10HD (504115), LS14EAI/AU (504116), LS14EA/60 (504117), LS10UK/1 (504118), LS10UK/3 (504119), LS12INS (504120), LS12 (504121), LS12DP (504122), LS12/60HZ (504125), LS12CW (504128), HT1200DEK (504129), LS14EAASIA (504131), LS14EA/G (504133), WT60DP (504134), WT60 (504135), WT60CW (504136), WT60UKDPCW (504137), WT60INS (504138), WT60INSCW (504139), WT60NAUCW (504140), WT60NAU (504141), LS10EA (504142), WT60/60HZ (504145), WT60/60HZC (504146), WT60N (504151), WT609NINS (504152), LS12HD (504153), LS14EAI/DD (504155), WT65E (504156), WT65EB (504157), WT65EI (504158), WT60NAUDP (504159), LS12UK/3CW (504161), LS12NAU (504163), LS12UKDPCW (504164), ECOTEMP12S (504165), WT65EBI (504166), WT65EBIA (504167), WT65EIA (504168), WT65E60 (504169), WT65EB60 (504170), WT60U40050 (504171), WT60U44060 (504172), WT65EBIDG (504173), WT65EBASIA (504174), WT65EIM50 (504175), WT65EIM60 (504176), WT60MX2206 (504177), LS12CWINS (504178), LS14EADP/G (504179), WT65MED (504180), WT65EJ50 (504183), WT65EJ60 (504186), LS14AH240U (504187), WT65H208U (504188), WT65H240U (504189), LS12ASIA (504190), WT60ASIA (504191), LS14H208DU (504194), LS14AH208U (504195), LS14H240DU (504196), LS14H208RU (504197), LS14H240RU (504198), WT65H208DU (504199), WT65H240DU (504200), WT65H208RU (504201), WT65H240RU (504202), WT65M208U (504203), WT65M240U (504204), WT65M208DU (504205), WT65M240DU (504206), WT65M208RU (504207), WT65M240RU (504208), LS14EAWS (504209), LS14ADPWWSG (504210), LS14EAIWS (504211), WT65EBWS (504212), WT65BIDWSG (504213), WT65EBIWS (504214), WT65MEDWS (504215), WT65H208WS (504216), WT65H240WS (504217), ET12EWS (504218), WT65ROW (504219), LS14ROW (504220), LS14SANA (504221), WT65EBID (504222), WT65EBIWS (504223), LS14ROW60 (504224), WT65ROW60 (504225), EHTA (504226), EHTA60 (504227), EHTAWS (504228), EHTAI (504229), EHTAID (504230), EHTAIWS (504231), EHTAIDWS (504232), EHTAIG (504233), EHTAIWSG (504234), EHTAIU (504235), EHTAIMLAU (504236), ZHTAWS (504237), ZHTAID (504238), ZHTAIWS (504239), ZHTAIU (504240), ZHTA (504241), ZHTA60 (504242), ZHTAI (504243), EHTAIUSPH5 (504244), EHTAIUSPH6 (504245), LS9P (505022), LS9PDD (505033), LS9AUK/3 (505034), LS9P60 (505035), EHTAO (505036), WT55P (505038), WT55P60 (505039), WT55AUK/3 (505040), LS9ADG1 (505041), WT55ADG1 (505042), LS9PAUS (505043), WT55PM50 (505044), WT55PM60 (505045), EHT (505046), EHT60 (505047), EHTG (505048), EHTM (505049), EHTM60 (505050), NHT (505051), NHTD (505052), NHT60 (505053), EHTAROW (505054), EHTAROW60 (505055), ZHTAROW (505056), ZHTAROW60 (505057), EHTAJ (505058), EHTAJ60 (505059), EHTAO60 (505060), ZHTAO (505061), ZHTAO60 (505062), KHT (505063), NHTM (505064), NHTM60 (505065), NHTP (505082), ZHT7 (505087), ZHT76 (505088), H2500 (698008), H3500 (698009), HT1200WS (698012), HT1200IWS (698013), H1510SANA (698017), LV1200IWS (698018), HT900 (698022), LV900P (698023), LD900 (698024), HT900ADG1 (698028), HT1200BIDG (698029), HT1200BIDW (698038), OHTAROW (698047), OHTAROW60 (698048), HT1200 (698050), HT1000 (698051), HT1000INS (698052), HT1200INS (698053), HT1000DP (698054), HT1200DP (698055), ET12EIG (698056), ET12EI (698057), NHTDPDDG (698058), LV1000 (698059), LV1200INS (698060), ET12EICWG (698061), ET12EICW (698062), ET12EIWS (698063), ET12EIF (698065), ET12AI (698097), ET12AIT (698098), NHTG (698110), AHTAWS (698115), AHTAIWS (698116), AHTAIG (698117), AHTAIWSG (698118), AHTA (698119), AHTAI (698120)

Relateret produkter:**Billede:**

