

# Produktinformation:

**Varenavn:**

Vaskepumpe FIR 2254/SSX 2HP 1.5 kW

**Varenr:**

G0274

**Pris:**

5.095,00 DKK /stk

**Link:**

<https://gastroparts.dk/shop/p/vaskepumpe-fir-2254-ssx-2hp-1-5-kw-G0274>

**Beskrivelse:****Mål:**

- Længde: 325 mm
- Bredde: mm
- Højde: mm
- Vægt: 12000 gr

**Fabrikater:**

- ALPENINOX
  - ELECTROLUX / ZANUSSI
- LS10D (504000), LS10 (504001), LS10UKRP (504002), LC100 (504003), ECOTEMP12- (504004), LS10/60 (504005), LS10/1 (504006), LS10/12KW (504007), LS10F (504008), LS10DEK (504009), LS10/1UKRP (504010), LS10SW (504011), LS10/50J (504012), LS10/60J (504013), LS10DP (504014), LS10/HD (504015), SH55 (504016), LO10 (504017), LS10/UK1 (504018), LS10/UK3 (504019), LS12D (504020), LS12 (504021), LS12UK/RP (504022), LC120 (504023), LS12DP (504024), LS12/60 (504025), LS12F (504028), LS12DEK (504029), LS12HD (504053), LS12/UK3 (504061), ECOTEMP12SW (504063), ECOTEMP12INS (504065), LS12MEX (504078), LS10N (504080), LS10 (504100), LS14EA (504101), LS10UKDP (504102), ET12E (504104), LS10/60HZ (504105), LS10CW (504107), LS10INS (504108), HT1200INS (504109), LS14EAI (504110), LS10N (504111), LS10DP (504114), LS10HD (504115), LS14EAI/AU (504116), LS14EA/60 (504117), LS10UK/1 (504118), LS10UK/3 (504119), LS12INS (504120), LS12 (504121), LS12DP (504122), LS12/60HZ (504125), LS12CW (504128), HT1200DEK (504129), LS14EAASIA (504131), LS14EA/G (504133), WT60DP (504134), WT60 (504135), WT60CW (504136), WT60UKDPCW (504137), WT60INS (504138), WT60INSCW (504139), WT60NAUCW (504140), WT60NAU (504141), LS10EA (504142), WT60/60HZ (504145), WT60/60HZC (504146), WT60N (504151), WT609NINS (504152), LS12HD (504153), LS14EAI/DD (504155), WT65E (504156), WT65EB (504157), WT65EI (504158), WT60NAUDP (504159), LS12UK/3CW (504161), LS12NAU (504163), LS12UKDPCW (504164), ECOTEMP12S (504165), WT65EBI (504166), WT65EBIA (504167), WT65EIA (504168), WT65E60 (504169), WT65EB60 (504170), WT60U40050 (504171), WT60U44060 (504172), WT65EBIDG (504173), WT65EBASIA (504174), WT65EIM50 (504175), WT65EIM60 (504176), WT60MX2206 (504177), LS12CWINS (504178), LS14EADP/G (504179), WT65MED (504180), WT65EJ50 (504183), WT65EJ60 (504186), LS12ASIA (504190), WT60ASIA (504191), WT65ROW (504219), LS14ROW (504220), LS14SANA (504221), WT65EBID (504222), LS14ROW60 (504224), WT65ROW60 (504225), H3500 (698009), H1510SANA (698017), HT1200elm (698020), HT1000elm (698021), HT1200BIDG (698029), HT1200 (698050), HT1000 (698051), HT1000INS (698052), HT1200INS (698053), HT1000DP (698054), HT1200DP (698055), ET12EIG (698056), ET12EI (698057), LV1000 (698059), LV1200INS (698060), ET12EICWG (698061), ET12EICV (698062), ET12EIF (698065), HYDRA1200 (727020), HYDRA1000 (727021), LSCE10 (777410), LSCE12 (777420)
- FIR

**Relateret produkter:****Billede:**